

現況写真

① (ランタの館)



⑤ (レントラ)



② (本館)



⑥ (本館)



③ LPガス容器置場



⑦ 入り口日除け



④ (レントラ)



⑧ 駐輪場



現況写真

⑨ 看板1



⑬ (ランタの館) (実習室)



⑩ 看板2



⑭ (ランタの館) (ボイラー室)



⑪ (ランタの館) (玄関)



⑮ (ランタの館) (女湯更衣室)



⑫ (ランタの館) (厨房)



⑯ (ランタの館) (女湯浴室)



現況写真

⑰ (ランタの館) (女湯露天風呂)



⑳ 連絡用通路 (内部)



⑱ (ランタの館) (男湯更衣室)



㉑ (本館) (連絡用通路連結部)



㉒ (ランタの館) (男湯浴室)



㉓ (本館) (1階廊下)



㉔ (ランタの館) (男湯露天風呂)



㉕ (本館) (機械室)




現況写真

②⑤ (本館) (2階廊下)




②⑨ (本館) (男子トイレ)



②⑥ (本館) (客室)



③⑩ (本館) (女子トイレ)



②⑦ (本館) (客室)



③① (本館) (2階ホール)



②⑧ (本館) (洗面台)



③② (本館) (1階ロビー)



現況写真

③③ (本館) (2階和室)



③⑦ (本館) (1階食堂)



③④ (本館) (2階和室)



③⑧ (本館) (本館・レントラ連絡通路)



③⑤ (本館) (1階厨房)




③⑨ (レントラ) (食堂)



③⑥ (本館) (1階厨房)



④⑩ (レントラ) (2階廊下)



現況写真

④① (レントラ) (2階交流ホール)




④⑤ (レントラ) (2階女子トイレ)



④② (レントラ) (2階トイレ)



④⑥ (レントラ) (客室)



④③ (レントラ) (2階身障者用トイレ)



④⑦ (レントラ) (客室)



④④ (レントラ) (2階男子トイレ)



④⑧ (レントラ) (客室)



現況写真

④⑨ (レントラ) (客室)



53 (レントラ) (1階廊下)



⑤⑩ (レントラ) (客室 トイレ)




54 (レントラ) (1階スロープ)



51 (レントラ) (3階廊下)



55 入り口階段日除け



52 (レントラ) (3階バルコニー)



56 入り口階段日除け

